



NOTES:

1. REMOVE JUMPER JA TO PREVENT HANDSWITCH INITIATED MOTION
2. J1 AND J2 ARE REQUIRED AS SHOWN
3. 120VAC ERROR ALARM AVAILABLE BETWEEN TERMINALS B AND E.

AUXILIARY SWITCH CONFIGURATION

	FORM A	FORM B
S1	<input type="checkbox"/>	<input type="checkbox"/>
S2	<input type="checkbox"/>	<input type="checkbox"/>
S3	<input type="checkbox"/>	<input type="checkbox"/>
S4	<input type="checkbox"/>	<input type="checkbox"/>

UNUSED

CC	FF	GG
HH	JJ	KK
MM	NN	PP

17-5509-550 E

SIZE:

A

THIS DOCUMENT IS A COPY AND IS NOT THE SOURCE DOCUMENT. INFORMATION IS SUBJECT TO CHANGE WITHOUT NOTICE. THE INFORMATION CONTAINED HEREIN IS COPYRIGHTED BY HAROLD BECK AND SONS, INC. CHANGES TO THE DOCUMENT ARE PROHIBITED. CONTACT A BECK SALES ENGINEER IF A CERTIFIED DRAWING IS REQUIRED.

HAROLD BECK & SONS INC

NEWTOWN INDUSTRIAL COMMONS NEWTOWN, PENNSYLVANIA 18940 USA

TITLE:

WIRING DIAGRAM GROUP 11-2X9/3X9/409/419/469/489
120 VOLT 4 AUX SWITCHES INT CPS
W/ H/S AUX CLSD IN AUTO W/ HART/LOCAL DCM

DRAWN:
GMD 2/20/04

SCALE:
NONE

DRAWING NO:

17-5509-550

REV:

E

CHECKED:
DMS 2/20/04

APPROVED:
JHM 2/20/04

SHEET NO. 1 OF 1